#### **POND 1 NOTES**

1.0 GENERAL FACILITY DESCRIPTION

POND 1 IS A DETENTION AND WATER QUALITY FACILITY THAT SERVES THE SOUTH PORTION OF THE WILD PLUM PROJECT. THE POND WAS DESIGNED PER UDFCD FULL SPECTRUM PROCEDURES AND UTILIZES THE SAND FILTER CONCEPT FOR WATER QUALITY TREATMENT. STORMWATER IS RELEASED AT A CONTROLLED AND ALLOWED RATE VIA TWO OVERFLOW WEIRS TO COOLEY LAKE.

#### 2.0 GENERAL INFORMATION A. UDFCD DRAINAGEWAY # NOT APPLICABLE

B. PROPERTY OWNER: WILD PLUM METROPOLITAN DISTRICT

C. DESIGN ENGINEER ENERTIA CONSULTING GROUP, LLC

(720) 250-8305

#### 3.0 HYDRAULIC INFORMATION

#### A. ONLINE OR OFFLINE FACILITY? OFFLINE

## B. FLOW RATES

0-1 CFS 0-1 CFS NORMAL LOW -FLOW 100-YEAR 81.8 CFS 34.8 CFS

## C. POND DESCRIPTION

REFER TO THE "POND 1 SUMMARY TABLE" ON THIS SHEET FOR STAGE AND VOLUME INFORMATION.

#### TWO SOIL RIPRAP SPILLWAYS. THE SPILLWAYS ARE SIZED TO DISCHARGE THE TOTAL ALLOWED OUTFLOW FROM POND 1 (34.8 CFS TOTAL)

THE WATER QUALITY ASPECT OF POND 1 IS DESIGNED AS A SAND FILTER WITH A 12 HOUR DRAIN TIME..

#### 4.0 MISCELLANEOUS INFORMATION

A. PROJECT SURVEY: (TOPOGRAPHY)

EXISTING TOPOGRAPHY WAS PROVIDED WITH AN ALTA SURVEY PREPARED BY CVL CONSULTANTS AND WAS PREPARED BASED ON AERIAL SURVEY. SUPPLEMENTAL AND SUPPORTING FIELD SURVEY WAS COLLECTED BY AZTEC CONSULTANTS, INC.

#### (PROJECT BENCHMARK)

THE ELEVATIONS AND CONTOURS AS SHOWN, ARE BASED UPON NGS STATION KNOWN AS Q23, BEING A 3" BRASS CAP SET IN CONCRETE LOCATED BETWEEN THE EGE OF ASPHALT OF NORTHBOUND SANTA FE DRIVE AND THE RAILROAD APPROXIMATELY 800 FEET SOUTH OF MINERAL AVENUE.

ELEVATION = 5,395.24 DATUM = NAVD 88

### B. SEED MIXES:

RIPARIAN SEED MIX							
COMMON NAME	SCIENTIFIC NAME	PERCENT BY WEIGHT	PLS lbs/acre	GROWTH SEASON	MIN. PRECIP (IN)		
ANNUAL RYEGRASS	LOLIUM PERENNE SSP. MULTIFLORUM	26%	8	C			
NEBRASKA SEDGE	CAREX NABRASCENSIS	3%	1	С	14-W		
SPIKE RUSH	ELEOCHARIS PALUSTRIS	1%	0.2	С	16-W		
SWITCHGRASS	PANICUM VIRGATUM	1%	0.25	W	12-W		
WESTERN WHEATGRASS	PASCOPYRUM SMITHII	20%	6	С	10		
FOXTAIL BARLEY	HORDEUM JUBATUM	13%	4	С	20-W		
BALTIC RUSH	JUNCUS BALTICUS	1%	0.2	С	7-W		
BUFFALOGRASS	BUCHLOE DACTYLOIDES	2%	0.5	W	7		
BEBB'S SEDGE	CAREX BEBBII	3%	1	С	14-W		
BLUE GRAMA	BOUTELOUA GRACILIS	2%	0.5	W	7		
ALAKALI SACATON	SPOROBOLUS AIROIDES	3%	1	W	5		
LITTLE BLUESTEM	SCHIZACHYRIUM SCOPARIUM	13%	4	W	43450		
INLAND SALTGRASS	DISTICHLIS SPICATA	10%	3	W	5-W		
SAND LOVEGRASS	ERAGROSTIS TRICHODES	3%	1	W	14		
PLS LBS/ACRE		100%	30.65				

	WILDFLOWERS						
COMMON NAME	SCIENTIFIC NAME	PERCENT BY WEIGHT	PLS lbs/acre	COLOR	BLOOM SEASON		
ARROWLEAF BALSOMROOT	BALSAMORHIZA SAGITTATA	3%	0.5	YELLOW	SUMMER		
BLACK-EYED SUSAN	RUDBECKIA HIRTA	1%	0.2	YELLOW	SUMMER/FALL		
SMOOTH ASTER	ASTER LAEVIS	13%	2	BLUE	FALL		
MOUNTAN LUPINE	LUPINUS ALPESTRIS	67%	10	BLUE	SUMMER		
ROCKY MOUNTAN PENSTEMON	PENSTEMON STRICTUS	7%	1	BLUE	SUMMER		
FIREWEED	EPILOBIUM ANGUSTIFOLIUM	1%	0.2	RED	SUMMER/FALL		
MILKWEED	ASCLEPIA SPECIOSA	3%	0.5	RED	SUMMER/FALL		
SCARLET BUGLER	PENSTEMON BARBATUS	3%	0.5	RED	SUMMER		
PLS LBS/ACRF		100%	14.9				

IT IS NOT ANTICIPATED THAT THE POND 1 AREA WILL BE MOWED. POND 1 SEEDING INCLUDES A NATIVE RIPARIAN AND WILDFLOWER SEED MIX

# 5.0 MAINTENANCE NOTES & PROCEDURES

PROVIDED TO LESSEN LONG TERM MAINTENANCE REQUIREMENTS.

THE FOLLOWING ITEMS SHOULD BE INSPECTED A MINIMUM OF ONCE PER YEAR AND MAINTAINED AS NEEDED: -POND BOTTOM - THE POND BOTTOM SHALL BE INSPECTED FOR SEDIMENT AND DEBRIS BUILD-UP. WHEN SEDIMENT BUILD-UP IMPEDES THE FUNCTION OF THE POND, THE SEDIMENT SHALL BE REMOVED AND DISPOSED OF OFF-SITE. ALL DEBRIS SHALL BE COLLECTED AND DISPOSED OFF-SITE.

-<u>VEGETATION</u> - THE POND VEGETATION SHALL BE UNIFORM AND IN GOOD HEALTH. REVEGETATE AREAS AS NEEDED. -EROSION - INSPECT THE POND AND SPILLWAY OUTFALLS FOR SIGNS OF EROSION. AREAS THAT ARE ERODED SHALL BE REPAIRED AND REVEGETATED. AREAS PRONE TO EROSION OVER AN EXTENDED PERIOD OF TIME SHALL BE REPAIRED AS NEEDED VIA SOIL RIPRAP, EROSION CONTROL BLANKET OR OTHER STABILIZATION METHOD.

-BUFFER FENCE ALONG COOLEY - THE BUFFER FENCE ALONG COOLEY LAKE IS A 3 RAIL FENCE WITH 12.5 GAUGE 2"X4" GALVANIZED WELDED WIRE FENCING. THE FENCE IS PROVIDED TO KEEP PEOPLE AND THEIR PETS AWAY FROM COOLEY LAKE. THE FENCE SHALL BE INSPECTED AND REPAIRED AS NEEDED TO MAINTAIN THIS PURPOSE. -SPILLWAY - THE SPILLWAY SHOULD BE INSPECTED FOR DEBRIS AND SEDIMENT BUILD-UP AS WELL AS EROSION. THE PERFORMANCE OF THE SPILLWAY SHALL BE MAINTAINED BY ADHERING TO THE

DETAILS AND DIMENSION SHOWN ON THIS PLAN. -UNDERDRAIN SYSTEM - THE UNDERDRAIN SYSTEM CANNOT BE PHYSICALLY INSPECTED, HOWEVER, THE FUNCTION OF THE POND SHALL BE MONITORED. IF THE POND DOES NOT APPEAR TO FUNCTION PROPERLY, AND ESPECIALLY IF IT HOLDS WATER OVER AN EXTENDED PERIOD OF TIME (GREATER THAN 40 HOURS), THAT IS A SIGN THAT THE UNDERDRAIN SYSTEM MAY NEED TO BE CLEANED OUT.

B. MAINTENANCE FREQUENCY ROUTINE MAINTENANCE TASKS, INCLUDING MOWING AND DEBRIS REMOVAL, SHOULD BE PERFORMED ON AN AS-NEEDED BASIS. DEBRIS REMOVAL SHOULD BE DONE PRIOR TO THE SUMMER STORM SEASON AND FOLLOWING SIGNIFICANT RAINFALL EVENTS. IN ADDITION, THE PROPERTY OWNER SHOULD PERFORM SITE INSPECTION ON AN ANNUAL BASIS TO EVALUATE THE NEED FOR ADDITIONAL MAINTENANCE, INCLUDING SEDIMENT REMOVAL, EROSION CONTROL, REVEGETATION AND STRUCTURAL REPAIRS.

# C. EQUIPMENT AND SPECIAL TOOLS REQUIRED

-LONG-REACH RAKE OR BROOM -LONG-REACH TRACK EXCAVATOR

-DUMP TRUCK

# 6.0 POND 1 USE RESTRICTIONS

THE FOLLOWING IS RESTRICTED IN AND AROUND THE AREA OF POND 1:


CLEAN-OUTS ARE PROVIDED TO ALLOW FOR THIS MAINTENANCE.

-THE USE OF FERTILIZERS -THE USE OF PESTICIDES

-PETS ARE NOT ALLOWED OFF-TRAIL AND ESPECIALLY WITHIN POND 1 OR NEAR COOLEY LAKE. PET WASTE MUST BE COLLECTED AND DISPOSED OF AT DESIGNATED LOCATIONS OR OFF-SITE.

# WILD PLUM POND 1 MAINTENANCE SITE PLAN

(PROJECT COMPLETED 2019)



⊢6" SOIL

\*34.8 CFS IS THE TOTAL ALLOWED DISCHARGE **KEY MAP** FROM POND 1. EACH SPILLWAY CONVEYS HALF OF THIS FLOW, 17.4 CFS, AT THE 100-YR WSE. NOTE THAT THE EXISTING DISCHARGE TO COOLEY LAKE

ITEM

100-YR WSE

**EURV WSE** 

100-YR VOLUME

**EURV VOLUME** 

BOT. OF POND ELEV

100-YR DEVELOPEI

INFLOW TO POND


100-YR DISCHARGE FROM SPILLWAYS\*

WAS ESTIMATED TO BE 54.6 CFS.


TOP OF POND ELEV

SPILLWAY SIZING TABLE							
SPILLWAY	LENGTH	WIDTH	SPILLWAY	TOP OF POND	SIDE SLOPE		
ID	(FT)	(FT)	ELEV.	ELEV.	(H:V)		
NORTH	SEE PLANS	3	5348.50	5349.25	20		
SOUTH	SEE PLANS	3	5348.50	5349.25	20		

-50-60' WIDE BENCH-



SCALE: 1"=30'




UNPLATTED

8" PVC UNDERDRAIN

OUTFALL TO LAKE

WSEL=5343.5±

OUTFALL TO LAKE



VERIFY SCALE BAR IS ONE INCH ON ORIGINAL DRAWING. MAINTENACI PLAN/N/N/G 43 OF 50

REUSE OF DOCUMENTS: THIS DOCUMENT, AND THE IDEAS AND DESIGNS INCORPORATED HEREIN, AS AN INSTRUMENT OF PROFESSIONAL SERVICE, IS THE PROPERTY OF ENERTIA CONSULTING GROUP AND IS NOT TO BE USED, IN WHOLE OR IN PART, FOR ANY OTHER PROJECT WITHOUT THE WRITTEN AUTHORIZATION OF ENERTIA CONSULTING GROUP