#### APPLICATION FOR COLORADO STATE INCOME TAX CREDIT FOR THE PRESERVATION OF HISTORIC STRUCTURES (RESIDENTIAL PROPERTY – 2014 CREDIT)

Pursuant to House Bill 14-1311 (CRS 39-22-514.5)

#### PART 2 -- FINAL APPROVAL

County:	Zip:
ming the credit)	
Limited	
Subchapter S	
applicant is not an indivi	dual):
Stata	7in:
State.	Zip:
State:	Zip:
	•
al Security Number):	
nber for all taxpayers in	de on a separate sheet the ntending to claim the credit.
er than owner (if owner is	s applicant, write same )
State:	Zip:
	r
Other (specify below)	
State:	Zip:
	Limited Subchapter S applicant is not an indivi State:  State:  O claim the credit, inclumber for all taxpayers in the credit owner is state:  State:

5. PROJECT STARTING DATE: PROJECT COMPLETION DATE:
6. PHOTOGRAPHS OF THE PROPERTY MUST BE INCLUDED (see instructions)
7. PROJECT COSTS Itemized:
Total qualified costs:
Total project cost:
8. APPLICANT'S SIGNATURE  I hereby attest that I am the property's owner or a qualified tenant with a lease of five or more years, that all work on this project has been completed and executed according to the proposed project description as stated in Part 1 and approved by the Reviewing Entity, and that all itemized costs are allowable to claim for tax credits under CRS 39-22-514.5 (2)(k)(II). I hereby agree to allow representatives of the reviewing entity access to the property as may be necessary and reasonable for the final approval of the completed work.
Signature: Date:

#### THE NYMAN HOUSE 5475 S MOHAWK ROAD LITTLETON, CO 80123

**DESCRIPTION OF REHABILITATION** 

#### UNDERSLAB DUCT WORK REPAIR



EXISTING FLOOR REGISTERS CONNECTED TO UNDERSLAB DUCT WORK




EXISTING FLOOR REGISTERS CONNECTED TO UNDERSLAB DUCT WORK




EXISTING FLOOR REGISTERS CONNECTED TO UNDERSLAB DUCT WORK


#### UNDERSLAB DUCT WORK REPAIR



## UNDERSLAB DUCT WORK REPAIR - COMPLETED WORK





RUSTED THROUGH PORTIONS OF DUCT SEALED WITH LIQUID LATEX



#### **SKYLIGHT**







EXISTING
DISCOLORATION AND
DAMAGE TO SKYLIGHT
FROM INTERIOR

#### SKYLIGHT -REPLACEMENT



290 East 56th Avenue Denver, CO 80216 303-296-9696 dalyteusa.com

Salesperson:	
E-Mail:	

### CURB MOUNT SKYLIGHT WORKSHEET

Sold To:		Phono		Fax:
		·		State: Zip:
Contact:	Project/P	O:	E-Mai	l:
See B	elow (In Inches)	Custom Dome Height 20-25% of smaller dimension if not specified		Other Notes
24"x24	<sup>"</sup> X			
	Χ			
	Χ			
	Χ			
Skylight Type: (Choose One)  Standard Acrylic Dome  Optional Acrylic Pyramid 6:12 Standard Slope  Optional Flat 2:12 Minimum Slope  Optional Custom Shape	Frame and Retainer Finish:  (Choose One)  Lear Anodized  Dark Bronze Anodized  Custom Frame Finish:	Glazing: (Choose One Standard Double Acrylic Clear over Clear Bronze over Clear Clear over White Optional Single Acrylic D Clear Bronze White Optional: Flat Insulated Glass Standard Glass Optional Bronze Custom: Flat Multiwall Transluce Polycarbonate Panel Standard Glass Clear Opal (White) Bronze Custom: Optional: Standard Glass Standard Glass Optional Bronze Custom: Standard Glass Standard Glass Optional Glass Standard Gl	Dome  Dome	OSHA Fall-Guard Protection:  YES: Include Optional Custom OSHA Fall—Guard Protection.  FALL—GUARD (SHIPPED LOOSE), GALVANIZED FINISH  OSHA Fall—Guards NOT Needed Because There Are Other Types of OSHA Fall Protection By Others.  Optional Dome Upgrade:  High Impact (Outer Dome)  Clear White Installation Supplies:  Installation Kit  -3/4" Wide x 1/4" High x 35' Long Curb Gasket, and -(20) #10x2" PPH SMS Installation Screws
STANDARD OUTER ACRYLIC DOME INNER  MOUNTING SCREWS BY INSTALLER. TYPICAL #10x2"  DALYTE ADDS 5/8"  CLEARANCE ON ALL SIDES (STANDARD)  CURB FLASHING (BY OTHERS)		OUTSIDE CURB DIMENSION (OCD)		OPTIONAL FLAT INSULATED GLASS OR MULTIWALL POLYCARB.  SILICONE SEALANT OR CURB GASKET BY INSTALLER  ASSEMBLY SCREWS  DALYTE ADDS 5/8"  CLEARANCE ON ALL SIDES (STANDARD)  WOOD CURB (BY OTHERS)
Approved By:	actured by Delute Description	Helle consist of an entered of the	- 6067 TC	Date: Inner frame (0.070") with a polyurethane thermal-break
to reduce thermal transfer throug withstand 40 P.S.F downward, and Dome units shall consist of an ac	hout the aluminum frame, and to I 20 P.S.F. outward loading and co crylic thermal—formed free blown o	minimize condensation in the interior fi onstructed to minimize air infiltration wi	rame. Outer th provisions is determine	inner frame (U.07) with a polyurethane thermal-break frame (0.060") thick. Skylights are constructed to for adequate moisture weeping to exterior. d by overall size with peel-off protective film. Glass

Note: Condensation is not a skylight defect, it is a result of atmospheric conditions inside and outside of the building. Skylights are designed to structurally account for expansion and contraction. Occasionally there may be audible popping noises especially with acrylic domes. All skylight glazing (transparent material) will have minor distortion especially when viewing at an angle. Tolerances are +/- 3/16".

DALYTE Skylights are not designed to support people. OCHA approved safety devices are to be used around skylight for personal safety. This worksheet will supersede all details on quotation — Please double check for accuracy.

v: 092222

#### SKYLIGHT -REPLACEMENT





NEW SKYLIGHT FROM EXTERIOR

#### FIREPLACE DAMPER



APPROXIMATE LOCATION OF EXISTING BROKEN DAMPER INSIDE CHIMENY FLUE


EXISTING CHIMNEY CAP





BROKEN DAMPER INSIDE CHIMNEY FLUE

#### FIREPLACE DAMPER





**Planet Duct** 

Brent Forget 5475 S Mohawk Rd Littleton, CO 80123

(636) 346-8982

bdforget@gmail.com

INVOICE #9020
SERVICE DATE Jun 13, 2023
DUE Upon receipt

AMOUNT DUE \$0.00

CONTACT US

3328 Adobe Court Colorado Springs, CO 80907

(719) 728-5111

office@planetduct.com

#### **INVOICE**

Services	qty	unit price	amount
Duct Renovation - Duct Armor - Subterranean  Approx 190 linear feet of ducting using about 20 gallons of Duct Armor.	1.0	\$6,900.00	\$6,900.00
Subterranean ducts can often deteriorate over time due to water, pests and settling or simply the ductwork. When this happens the ductwork can become unusable or dangerous to the hea			

Duct Armor creates an encapsulating liner that prevents any further deterioration of the duct system and allows you to use your underground ducts for many years to come. Service includes a camera scope of the system as well as applications of the liner roughly. There will be a smell like paint for a few days after applying the liner but once fully cured there is no odor.

Duct Cleaning before application is required and system being completely dry prior to application is required.

The client may need to "quikcrete" areas under the registers of bare earth is visible pryor to duct armor application.

#### Air Duct Cleaning - 1000 SF - 1799 SF included w Duct Armor 1.0 \$0.00 \$0.00

Air duct system cleaning with a powerful "Negative Air Pressure" system. The cleaning is performed to the standard established by NADCA (National Air Duct Cleaners Association).

Residential Air Ducts should be cleaned every 3-5 year or after any remodel or restoration work has been done. Air duct cleaning should also be done immediately before a new furnace is installed.

We clean the supply and return runs and the trunk lines with pneumatic agitation tools while our powerful Vacuum pulls the dust, dirt and debris out of your system. We also clean the blower wheel, blower compartment and the return drop. Don't be fooled by low price coupon book amateurs. Hire the Professionals at Planet Duct. Our pricing is based off square footage, not vents. So there is no need to count them. (see additional service items if you have more than 1 furnace or if your furnace is located in an attic or crawl space).

Work outside of the Colorado Springs Metro area may incur a trip charge.

#### Dryer Vent Cleaning - Dryer Vent Cleaning with Air Duct Cleaning 1.0 \$0.00 \$0.00

ONLY CHOOSE THIS OPTION IF WE ARE ALSO DOING WHOLE HOUSE AIR DUCT CLEANING AT THE SAME TIME.

Cleaning out your clothes dryer vent will make your dryer, dry clothes faster and make your dryer last longer. Cleaning your dryer vent will also reduce the risk of having a dryer vent fire. Clogged dryer vents are the #1 cause of home fires in the Unites States.

If your clothes are taking longer to dry, you should have the vent cleaned.

If the laundry room is getting very hot when you dry clothes, you should have the vent cleaned

If you notice a burning smell when you are drying clothes, you should have the vent cleaned immediately.

If you see allot of lint sticking out of the exhaust vent outside, you should have the vent cleaned.

If you cant remember that last time the vent was cleaned, you should have the vent cleaned.

Total \$6,900.00

Payment History

Jun 13 Tue 4:56pm Check \$6,900.00

Stronger Than The Vacuum Of Space!
Have your HVAC filters delivered to your door

and get automatic filter change email reminders.

Just go to: https://filterfetch.com/contractor-link/CD95

Cancellation policy: We do not cancel due to weather unless the roads are treacherous.

24 hours notice is required for cancellation or rescheduling your air duct cleaning or Aerosealing appointment. If an air duct cleaning or Aerosealing appointment is cancelled or rescheduled with less than 24 hours notice, a \$200 reschedule fee will be applied and prepayment will be required prior to service being rescheduled.








































# ACKNOWLEDGEMENT



#### P-15020

9/6/2023

BRENT FORLIET

To:

Chris Davis

BOSS Architecture 5475 Mohawk Rd

Littleton CO 80123-2940

303-377-6322 636-346-8987

chris@bossarch.com

From:

Garrett Gill

AiA Industries, LLC dba DĀLYTE

GGill@DalyteUSA.com

Project:	<b>Brent Forget</b>				
Description:					,
PO Number		Terms	Credit Card	Shipping Method:	Delivery

Quantity	Item	Unit Price	Total Amount
1	Installer	\$225.00	\$225.00
11	Curb Mount Skylight - Acrylic 24" x 24" Outside Curb Dimension Double Dome Bronze/Clear Clear Anodized Thermally Broken Aluminum Frame	\$289.25	\$289.25
1	Installation Kit for Curb Mount Skylights	\$25.00	\$25.00
	1	Subtotal	\$539.25
		Sales Tax	\$25.15
		Quote Total	\$564.40







Chimney Sweeps of America 5161 Ward Road Unit #8 Wheat Ridge, CO 80033 Phone: 303-973-7376 Fax: 303-227-7641 info@chimneysweepsofamerica.com

#### **Customer Information**

Brent Forget 5475 S Mohawk Rd Littleton, CO 80123

Phone: 636-346-8982

 Work Date
 Arive
 Team

 1/24/2024
 2:00 PM
 Tim's Truck

Summary: Install 13x13 Lock Top Damper

<sup>\*</sup>Inspection Report and/or Notes from the job are located directly below the Services/Products section.\*

Service/Product	Price	Qty	Amount
<b>13x13 Lock Top II Damper</b> Fits: 9x9 to 12.5x12.5 ID Cross Sectional Area: 100 sq. in. Includes EZ Open Damper Handle	\$775.00	1.00	\$775.00
Credit Card Transaction Fee  3% Credit Card Transaction Fee *Can be removed if paying with check or cash.*	\$23.25	1.00	\$23.25
	Subtotal		\$798.25
	Tax		\$0.00
	Total		\$798.25

Payment via No Payment, ending #, in the amount of \$0.00, was received on 1/24/2024.

#### **Inspection Report and/or Notes:**

A new 13" x 13" LockTop damper system was installed today. It acts as a flue cap and damper system all in one. It sits on top of the flu tile and it has a stainless steel wire that runs down the flu tiles into the fireplace with a new damper handle has been installed on the fireplace wall. It's bolted into the wall with two bolts. The damper on top seals itself when closed so it's airtight and prevents weather from accessing the fireplace.

**Payment Terms:** Non-refundable 50% required for booking and ordering parts. Remainder is due upon completion.

\*\*PAYMENT OPTIONS ARE AVAILABLE: 12 MONTH SAME AS CASH OR 5 YEAR 6.99% LOW MONTHLY PAYMENT. Please reply back to this e-mail or call for more information and qualification\*\*

Why choose Chimney Sweeps of America? All of our technicians are nationally certified by the Chimney Safety Institute of America. We are NFI certified specialists and installers in Gas, Wood, and Pellet fueled appliances and are the only company with multiple NFI Master Hearth Professionals on staff. We are a trusted name that has been serving the Denver area since 1982, a local family owned and operated business. We are annual service award winners with Angie's List and Home Advisor and have a A+ standing with the BBB. We are licensed, insured, and bonded and can provide any documentation when needed. We can provide referrals if requested as we've installed thousands of hearth and free standing appliances. We are proud members of the HPBA, NFPA, and the National Chimney Sweep Guild. We regularly continue our education to keep up with the ever changing codes and innovations in our industry to provide the most up to date and accurate information, products, and options for repairs and updates. Safety and education are our priorities and our customers are our passion.

Customer Signature:		
Date:	1/24/2024	
horoby acknowledge and agree to all nayment terms and conditions listed above		

I hereby acknowledge and agree to all payment terms and conditions listed above

Please fill out our <u>CUSTOMER SURVEY</u> as we greatly value your feedback. We appreciate your time and are constantly striving to meet and exceed your expectations.

<sup>\*</sup>All pictures (current conditions, final pictures, & recommended repairs) are located on the last page of this invoice.\*















Chimney Sweeps of America – 303-973-7376 – <u>www.chimneysweepsofamerica.com</u>

#### **Photos After**



